




27000711606 - W-Boss/827237/90/P



27001009700 - W-Boss/14216070G7/20/120



27000703300 - W-Boss/629028H7/8/90/HP

Partnumbers
for cast bosses:

Partnames
for cast bosses:

L: B: D: Bore:
min/max

27000701606	W-Boss/428246/90/P	42	82	46	SD - P1
27000701800	W-Boss/459067/90	45	90	67	SK - SF
27000710406	W-Boss/627323/90/P	62	73	23	23 - 48
27000711506	W-Boss/827227/90/P	82	72	27	27 - 37
27000711606	W-Boss/827237/90P	82	72	37	37 - 48
27000711806	W-Boss/1129037/90/P	112	90	37	37 - 41
27000712006	W-Boss/1129041/90/P	112	90	41	41 - 60
27000703400	W-Boss/609067/90/HP	60	90	67	SK - SF

Partnumbers
machined bosses:

Partnames
machined bosses:

L: B: D:

27001010000	W-Boss/4514075G7/20/90	45	140	75G7
27001002700	W-Boss/5213024H7/8/90	52	130	24H7
27000708207	W-Boss/1129042H7/12/90	112	90	42H7
27001008800	W-Boss/1129055G7/16/90	112	90	55G7
27001008300	W-Boss/1259042H7/12/90	125	90	42H7
27001009000	W-Boss/1259055G7/16/90	125	90	55G7
27001009100	W-Boss/1429060G7/18/90	142	90	60G7
27001009600	W-Boss/14213065G7/18/90	142	130	65G7
27001009700	W-Boss/14216070G7/20/120	142	160	70G7
27001009800	W-Boss/14216075G7/20/120	142	160	75G7
27001009900	W-Boss/14216080G7/22/120	142	160	80G7
27000703300	W-Boss/629028H7/8/90/HP	62	90	28H7
27000703200	W-Boss/829038H7/10/90/HP	82	90	38H7
27000703600	W-Boss/1129042H7/12/90/HP	112	90	42H7
27000703800	W-Boss/1129048H7/14/90/HP	112	90	48H7
27000706800	W-Boss/1129055G7/16/90/HP	112	90	55G7
27000707700	W-Boss/1429060G7/18/90/HP	142	90	60G7
27000707100	W-Boss/14213065G7/18/90/HP	142	130	65G7
27000707200	W-Boss/14213075G7/20/90/HP	142	130	75G7
27000707407	W-Boss/14216080G7/22/120/HP	142	160	80G7
27001005408	W-Boss/11274,838/10/90/Steel	112	74,8	38H7
27001005608	W-Boss/1129042H7/12/90/Steel	112	90	42H7

Last update: 21-07-2006


MULTI-WING
www.multi-wing.com